

Deutsch

SVFB News Flash

04-2021 / 28. Oktober 2021

Betrifft Helikopter-Wartungsbetriebe

Sehr geehrte SVFB Mitglieder
Sehr geehrte Damen und Herren

Gerne informiere ich Sie über das veröffentlichte EASA Emergency AD, welches heute durch das Bundesamt für Zivilluftfahrt (BAZL) publiziert wurde.
Betroffene Helikopter und entsprechende Komponenten entnehmen Sie bitte aus den nachfolgenden Informationen sowie dem Link zum Dokument.

Emergency Airworthiness Directive (Emergency AD)

AD No: 2021-0235-E


Issued: 28. Oktober 2021

Airbus Helicopters

Affected types: EC 130 – all serial numbers on which AH modification 074581 has been embodied in production.

ATA 53: Fuselage – Rear Transmission Bearing Support – Inspection

[Link zum Dokument](#)

RESPONSIBLE AUTHORITY & AD ref.	TC-HOLDER TYPE SUBJECT	ISSUE DATE
 EASA 2021-0235-E (PDF, 191 kB, 28.10.2021)	AIRBUS HELICOPTERS EC 130 T2 REAR TRANSMISSION BEARING SUPPORT	28.10.2021

Vielen Dank für Ihre Kenntnisnahme.

Mit freundlichen Grüssen

Balz Albertin



Geschäftsführer SVFB

Français

ASEA flash d'information

04-2021 / 28. octobre 2021

Concerne les entreprises de maintenance d'hélicoptères

Chers membres de l'ASEA
Mesdames et Messieurs

J'ai le plaisir de vous informer que des consignes de navigabilité urgentes (Emergency AD) de l'EASA ont été publiées aujourd'hui par l'Office fédéral de l'aviation civile (OFAC).

Les types de l'hélicoptère et des composants correspondants sont indiqués dans les informations suivantes ainsi qu'en cliquant le lien vers le document.

Emergency Airworthiness Directive (Emergency AD)

AD No: 2021-0235-E


Issued: 28 octobre 2021

Airbus Helicopters

Affected types: EC 130 – all serial numbers on which AH modification 074581 has been embodied in production.

ATA 53: Fuselage – Rear Transmission Bearing Support – Inspection

[Lien vers le document](#)

RESPONSIBLE AUTHORITY & AD ref.	TC-HOLDER TYPE SUBJECT	ISSUE DATE
 EASA 2021-0235-E (PDF, 191 kB, 28.10.2021)	AIRBUS HELICOPTERS EC 130 T2 REAR TRANSMISSION BEARING SUPPORT	28.10.2021

Merci beaucoup de votre attention.

Avec mes meilleures salutations

Balz Albertin



Directeur de l'ASEA

English

SAMA News Flash

04-2021 / 28 October 2021

Concerning helicopter maintenance companies

Valued members of SAMA
Dear Sir or Madam

I am pleased to inform you about the EASA Emergency AD, which was published today by the Federal Office of Civil Aviation (FOCA).

Affected helicopter types and corresponding components can be found in the following information and the link to the document.

Emergency Airworthiness Directive (Emergency AD)

AD No: 2021-0235-E


Issued: 28 October 2021

Airbus Helicopters

Affected types: EC 130 – all serial numbers on which AH modification 074581 has been embodied in production.

ATA 53: Fuselage – Rear Transmission Bearing Support – Inspection


[Link to document](#)

RESPONSIBLE AUTHORITY & AD ref.	TC-HOLDER TYPE SUBJECT	ISSUE DATE
 EASA 2021-0235-E (PDF, 191 kB, 28.10.2021)	AIRBUS HELICOPTERS EC 130 T2 REAR TRANSMISSION BEARING SUPPORT	28.10.2021

Thank you very much for taking note.

With kind regards

Balz Albertin



Director of SAMA